

## Annexure D

### BUILDING SAFETY CERTIFICATE

Certificate No.834/3/BSC-25

Dated: 05/04/2025


It is certified that the existing Building **CHANDRA INTERNATIONAL SCHOOL** (name of the building or premises) at **Chakmehadi, Maunath Bhanjan, Mau** (address) is having Block(s)/Floor(s) as per details below:

Detail of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor (s) in the Block	Ground floor + 3	-	-	-	-	-

The building is owned/occupied by **CHANDRA INTERNATIONAL SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Works Department, Mau** (Name of Department/Govt.) on **04/04/2025** (date of inspection) in the presence of **Vijay Bahadur Pal** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **05/04/2025** for a period of **10** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. ☐
2. ☐ All conditions fulfilled
3. ☐
4. ☐

Issued on **05/04/2025** at **Mau** by

Signature with Seal: 

Name: **Chakresh Ken**

Designation: **Executive Engineer**

Name & Address of Department/Office: **Provisional Division,**

**Public Works Department, Mau**